+7 (495) 734-91-88, +7 (495) 601-28-88
г. Москва, ул. Псковская, дом 5, корпус 1
E-mail: info@autodieselpart.ru

Генератор 14В 35А — 110128


https://autodieselpart.ru/product/?id=110128


Артикул

110128

Параметры

Бренд:	HC-CARGO
Качество:	Оригинал





Генератор 14В 35А 110128 (производитель HC-CARGO) . Срок поставки: в наличии и под заказ. Бесплатная доставка по Москве или до транспортной компании. Основные характеристики артикула 110128: Применяется на следующих марках: ATK, DAF, ISUZU, MASSEY FERGUSON (MF), MAZDA, MITSUBISHI, NISSAN, SUBARU. Применяется на следующих моделях: Chevrolet Luv 1.8 (01-01-1972 - 01-01-1981), Komatsu FG20-6 [Nissan H20PU] , Komatsu FG20-7 [Nissan H20PU] , Komatsu FG20-8 [Nissan H20PU] , Nissan Cherry 1.2 [A12] [VN10] (01-10-1978 - 01-07-1981), Nissan Cherry 1.2 [A12] [N10] (01-08-1978 - 01-07-1981), Nissan Sunny 1.4 [A14] [B310] (01-01-1970 - 01-02-1982), Nissan Cherry 1.0 [A10S] [N10] (01-08-1978 - 01-07-1981), Subaru GL 1.3 (01-01-1972 - 01-01-1972), Subaru GL 1.4 (01-01-1973 - 01-01-1974), Subaru Deluxe 1.3 (01-01-1972 - 01-01-1972), Subaru Deluxe 1.4 (01-01-1973 - 01-01-1973), Subaru DL 1.4 (01-01-1974 - 01-01-1974), Subaru Star 1.3 (01-01-1972 - 01-01-1972), TCM FG 20 , TCM FG 15 [A15]. Фото: 110128.

Применяемость

Марки (Brand):	ATK, DAF, ISUZU, MASSEY FERGUSON (MF), MAZDA, MITSUBISHI, NISSAN, SUBARU
Модели (Model):	Chevrolet Luv 1.8 (01-01-1972 - 01-01-1981), Komatsu FG20-6 [Nissan H20PU] , Komatsu FG20-7 [Nissan H20PU] , Komatsu FG20-8 [Nissan H20PU] , Nissan Cherry 1.2 [A12] [VN10] (01-10-1978 - 01-07-1981), Nissan Cherry 1.2 [A12] [N10] (01-08-1978 - 01-07-1981), Nissan Sunny 1.4 [A14] [B310] (01-01-1970 - 01-02-1982), Nissan Cherry 1.0 [A10S] [N10] (01-08-1978 - 01-07-1981), Subaru GL 1.3 (01-01-1972 - 01-01-1972), Subaru GL 1.4 (01-01-1973 - 01-01-1974), Subaru Deluxe 1.3 (01-01-1972 - 01-01-1972), Subaru Deluxe 1.4 (01-01-1973 - 01-01-1973), Subaru DL 1.4 (01-01-1974 - 01-01-1974), Subaru Star 1.3 (01-01-1972 - 01-01-1972), TCM FG 20 , TCM FG 15 [A15]
OE Внешние (OE External):	ATK: ADA3212, AMA360, ASA391, ASA390, ADA321, DAF: 1516847R, ISUZU: 8942060810, 9822007630, MASSEY FERGUSON (MF): 1691805R2, 1893705T, 968296M1, 968856M1, MAZDA: 032418400A, 028018400, 028018400A, 051218400, 060518400G, MITSUBISHI: A001T22581, A1T22581, AG2030A, AG2035A, AH2035N1, A001T20271, A1T20271, A1T21171, A1T24471, A001T21171, A001T24471, AG2025A, AG2035A2, NISSAN: 2310090060, 2310091004, 23100A4600, 23100A4601, 23100A4602, 23100A4611, 23100A5500, 23100A5501, 23100A5502, 23100H0310, 23100M0400, 23100M0401, 23100M0402, 23100M0403, 23100M0410, 23100M0412, 23100M0413, 23100M0414, 23100U0100, 23100U0101, 23100U0102, 23100U0103, 23100U0104, 23100U0105, 23100U0110, 23100U0111, 23100U0112, 23100U0113, 23100U0114, 23100UO112, 23100A4800, SUBARU: 329900100, 829906110

Аналоги (Analogues):	AC DELCO: DRA2431, AD KÃÅHNER: 40100, AD KÃÅHNER: 40105RI, AUTOSTARTER POLAND: A5164, BOSCH: 0986032431, BOSCH: 0986032451, BOSCH: 0986033481, BOSCH: AL231X, BOSCH: AL232X, BOSCH: F004BL0110, CASCO SRL: CAL35140, CASCO SRL: CST21184, CV PSH: 165002035, DELCO REMY: DRA2431, DRI: 227001302, DRI: 227103402, DRI: 233002402, DRI: 243005352, DRI: 243006302, DRI: 527003352, DRI: 243005532, ELSTOCK: 270521, ELSTOCK: 27522, EUROTEC: 11040058, EUROTEC: 12060208, EUROTEC: 12060308, EUROTEC: 12060434, EUROTEC: 12060534, FARCOM: 118123, FARCOM: 118661, FRIESEN: 2851100, FRIESEN: 9051100, HC-CARGO: 110128, HC-PARTS: JA100, HELLA: 8EL726256001, HERTH U. BUSS: J5111000, HITACHI AUTOMOTIVE SYSTEMS: LT12506, HITACHI AUTOMOTIVE SYSTEMS: LT12506B, HITACHI AUTOMOTIVE SYSTEMS: LT13072, HITACHI AUTOMOTIVE SYSTEMS: LT13075, HITACHI AUTOMOTIVE SYSTEMS: LT13081, HITACHI AUTOMOTIVE SYSTEMS: LT13513, HITACHI AUTOMOTIVE SYSTEMS: LT13513B, HITACHI AUTOMOTIVE SYSTEMS: LT13519, HITACHI AUTOMOTIVE SYSTEMS: LT13520, HITACHI AUTOMOTIVE SYSTEMS: LT13522, HITACHI AUTOMOTIVE SYSTEMS: LT13524, HITACHI AUTOMOTIVE SYSTEMS: LT13530, HITACHI AUTOMOTIVE SYSTEMS: LT13535, HITACHI AUTOMOTIVE SYSTEMS: LT13535B, HITACHI AUTOMOTIVE SYSTEMS: LT13535C, HITACHI AUTOMOTIVE SYSTEMS: LT13536C, HITACHI AUTOMOTIVE SYSTEMS: LT13554, HITACHI AUTOMOTIVE SYSTEMS: LT13569, HITACHI AUTOMOTIVE SYSTEMS: LT12565, HITACHI AUTOMOTIVE SYSTEMS: LT13072B, HITACHI AUTOMOTIVE SYSTEMS: LT13303, HITACHI AUTOMOTIVE SYSTEMS: LT13304, HITACHI AUTOMOTIVE SYSTEMS: LT13305, HITACHI AUTOMOTIVE SYSTEMS: LT13305B, HITACHI AUTOMOTIVE SYSTEMS: LT13516, HITACHI AUTOMOTIVE SYSTEMS: LT13519B, HITACHI AUTOMOTIVE SYSTEMS: LT13519C, HITACHI AUTOMOTIVE SYSTEMS: LT13519E, HITACHI AUTOMOTIVE SYSTEMS: LT13526, HITACHI AUTOMOTIVE SYSTEMS: LT13535A, HITACHI AUTOMOTIVE SYSTEMS: LT13536, HITACHI AUTOMOTIVE SYSTEMS: LT13083, ISKRA: MS206, LESTER: 14223, LESTER: 14213, LUCAS: LRA00107, LUCAS: LRA00227, MARELLI: 943346046010, MARELLI: 943346086010, QUINTON HAZELL: 9051100, QUINTON HAZELL: QA0328, SPIDAN: 3100, SUDEST: 55791, SUDEST: 56058, VALEO: 436502, VALEO: 436551, VALEO: 437149, VALEO: VA220, WAI: 1111101MI, WAI: 1111101HI, WAI: 1152401HI, WAI: 14105N, WAI: 14105R, WAI: 14213, WAI: 14213N, WAI: 14534N, WAI: 14588R
Описание/Технические характеристики (Description/Specifications):	Напряжение 14, Ампер 35, Регулятор без, Пазы/шкив 1, Отверстие кронштейна регулировки ремня 1 M8, Расстояние до кронштейна 80,50, Радиус 77,50, Диаметр шкива 62,00, Произв. информация BN, Размер отверстия кронштейна сзади 8,00, Шкив P, Расстояние между шкивами 42,00, Обслуживание Nissan, Chevrolet, Subaru, Позиция D+ 52, Номер разъема. 1 PL06, Вентилятор EF, Радиус 2 77,50, B+ M5, Вращение по часовой стрелке, Размер отверстия кронштейна 1 8,00, Ширина рычага держателя 13,00, Заглушка размера D+, Положение отверстия кронштейна регулировки ремня 60, Общая длина 161,00, Положение 50, Положение B+ 15